




პკ 1+75




პკ 2+00




პკ 2+25




პკ 2+50




პკ 2+75




პკ 3+23




პკ 3+25




პკ 3+50



პკ 3+75



პკ 4+00



სოფელ ნაგდარანთკარში შიდა საუბნო
გზების მოწყობა რეაბილიტაცია

განივი პროფილი
პკ 1+75 პკ 2+00 პკ 2+25 პკ 2+50 პკ 2+75
პკ 3+00 პკ 3+25 პკ 3+50 პკ 3+75 პკ 4+00



სტადია	ფურცელი	ფურცლების
	8	11
შ.პ.ს. "არქმშენი"		
2014 წელი		